

FIG. 2A




FIG. 2B








FIG. 3
















SILICA STRUCTURE CRACK MONITORING


CADET et al.

Serial No.: 09/852,420

Schnader, Harrison, Segal & Lewis, LLP (215) 751-2000 ref# 1525-00







9/12

FIG. 9A

WAVEFORM (mV) VS TIME (USED)




FIG. 9B

WAVEFORM (mV) VS TIME (USED)





FIG. 10






FIG. 12

